Date：2021/08/10

【Security Vulnerability Warning】Cisco RV340, RV340W, RV345 and RV345P Dual WAN Gigabit VPN routers exist security vulnerabilities (CVE-2021-1609 and 1610), please confirm and update as soon as possible!

Subject:【Security Vulnerability Warning】Cisco RV340, RV340W, RV345 and RV345P Dual WAN Gigabit VPN routers exist security vulnerabilities (CVE-2021-1609 and 1610), allowing attackers to remotely execute arbitrary code. Please confirm and update as soon as possible!

Description:
For details, please refer to the following links.

1. https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-rv340-cmdinj-rcedos-pY8J3qfy
2. https://www.ithome.com.tw/news/146036

Network System Division
Computer and Communication Center

From:
https://net.nthu.edu.tw/netsys/ - 網路系統組

Permanent link:
https://net.nthu.edu.tw/netsys/en:mailing:announcement:20210810_02

Last update: **2021/08/10 16:19**