

Date 2021/08/10

Security Vulnerability Warning Cisco RV340, RV340W, RV345 and RV345P Dual WAN Gigabit VPN routers exist security vulnerabilities (CVE-2021-1609 and 1610), please confirm and update as soon as possible!

Subject: Security Vulnerability Warning Cisco RV340, RV340W, RV345 and RV345P Dual WAN Gigabit VPN routers exist security vulnerabilities (CVE-2021-1609 and 1610), allowing attackers to remotely execute arbitrary code. Please confirm and update as soon as possible!

Description:

For details, please refer to the following links.

1. <https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-rv340-cmdinj-rce-dos-pY8j3qfy>
2. <https://www.ithome.com.tw/news/146036>

Network System Division
Computer and Communication Center

From:

<https://net.nthu.edu.tw/netsys/> - 網路系統組

Permanent link:

https://net.nthu.edu.tw/netsys/en:mailing:announcement:20210810_02

Last update: 2021/08/10 16:19

